







J. Fletcher Creamer  
 8" Main Installation along Jersey Avenue  
 Work Week of 09/23/2019



**Legend** Week of 09/23/2019

-  Location of Construction Activity
-  Western Transmission Main Alignment Previously Completed
-  Western Transmission Main Alignment

Sources: Esri, HERE, Garmin, GeoBase, IGN, Kadaster NL, OpenStreetMap contributors, and the GIS User Community