

J. Fletcher Creamer  
 Jack and Bore-Installation of 42" Carrier Pipe  
 Work Week of 12/16/2019



**Legend** Week of 12/16/2019

-  Location of Construction Activity
-  Western Transmission Main Alignment Previously Completed
-  Western Transmission Main Alignment




Sources: Esri, HERE, Garmin, GeoBase, IGN, Kadaster NL, OpenStreetMap contributors, and the GIS User Community