




J. Fletcher Creamer
 Disinfection of the 30" Main Along Jersey Ave
 Work Week of 03/30/2020

Week of 03/30/2020



Legend

- Location of Construction Activity
- Western Transmission Main Alignment Previously Completed
- Western Transmission Main Alignment

Sources: Esri, HERE, Garmin, GeoBase, IGN, Kadaster NL, OpenStreetMap contributors, and the GIS User Community